






LEISTER WELDMAX  
Accessories List 2009

Picture & Description:	
	<p>Welding shoe complete, for fillet weld WELDMAX</p> <p>112.630: Welding shoe complete, for fillet weld 5 mm (a = 3.5 mm)            112.625: Welding shoe complete, for fillet weld 6 mm (a = 4.2 mm)            112.627: Welding shoe complete, for fillet weld 8 mm (a = 5.6 mm)            112.628: Welding shoe complete, for fillet weld 10 mm (a = 7 mm)</p>
	<p>Storage case for WELDMAX</p> <p>112.852: Storage case</p>
	<p>Welding shoe complete, V-seam for WELDMAX</p> <p>112.629: Welding shoe complete, V-seam 5 mm            112.621: Welding shoe complete, V-seam 6 mm            112.623: Welding shoe complete, V-seam 8 mm            112.624: Welding shoe complete, V-seam 10 mm</p>
	<p>Welding shoe complete, overlapp for WELDMAX</p> <p>112.626: Welding shoe complete, overlap 20 mm</p>
	<p>Welding shoe blank for WELDMAX</p> <p>112.830: Welding shoe blank complete</p>

\*Pictures for illustrative purposes only and may differ from that shown.

January 2009