









LEISTER FUSION 2
Accessories List 2009

Picture & Description:	
	<p>Welding shoe complete, Fillet weld for FUSION 3</p> <p>118.887: Welding shoe complete, fillet weld 5/6 mm (a = 4.2 mm) 118.885: Welding shoe complete, fillet weld 8/10 mm (a = 7 mm) 119.139: Welding shoe complete, fillet weld 15 mm (a = 10.5) 119.140: Welding shoe complete, fillet weld 20 mm (a = 14 mm) 119.141: Welding shoe complete, fillet weld 25 mm (a = 17.5 mm) 119.142: Welding shoe complete, fillet weld 30 mm (a = 21 mm)</p>
	<p>Welding shoes blank complete 50x30x38mm for FUSION 3</p> <p>118.094: Welding shoe blank complete 50 x 30 x 38 mm</p>
	<p>Welding shoes blank complete 70x50x47.5mm for FUSION 3</p> <p>119.214: Welding shoe complete, blank 70 x 50 x 47.5 mm</p>
	<p>Welding shoe complete, V-seam for FUSION 3</p> <p>118.888: Welding shoe complete, V-seam 5/6 and X-seam 10/12 mm 118.889: Welding shoe complete, V-seam 8/10 and X-seam 15/20 mm 119.202: Welding shoe complete, V-seam 12 and X-seam 25 mm 119.203: Welding shoe complete, V-seam 15 and X-seam 30 mm 119.204: Welding shoe complete, V-seam 20 and X-seam 35/40 mm 119.205: Welding shoe complete, V-seam 25 mm 119.206: Welding shoe complete, V-seam 30 mm</p>
	<p>Welding shoe overlap 25 mm for FUSION 3</p> <p>118.890: Welding shoe complete, overlap 25 mm 119.185: Welding shoe complete, overlap 35 mm</p>
	<p>Welding rod de-reeler, Hand extruder</p> <p>118.188: Welding rod de-reeler</p>
	<p>Welding shoe complete, corner, short ø 20 mm</p> <p>129.008: Welding shoe complete, corner, short ø 20 mm</p>
	<p>Welding shoe complete, corner, long ø 14 mm</p> <p>129.010: Welding shoe complete, corner, long ø 14 mm</p>

*Pictures for illustrative purposes only and may differ from that shown.
January 2009